

# Office of the Chief Fire Officer Bengaluru-East Zone, Karnataka Fire & Emergency Services Department No. 04, Commissariat Road, Bengaluru-560 025.



No. 936(15)/CFO/Bng-East/FSR/2020

Dated: 22-12-2020.

## ANNEXURE - 1

# **Group - B Educational Building**

NBC-2016, Part-4, Table 7(11) 3.1.3 Group B Educational Buildings Sub Division B1 & B2. (These condition are indicative and not exclusive all relevant provisions related to fire and life safety of NBC-2016 are mandatory).

To,
The Principal,
M/s. RV College of Engineering,
R.V. Educational Institutions,
R.V. Vidyaniketana Post, Mysore Road,
Bangaluru-560059.

Sir,

Sub: Issue of "Fire Safety Recommendation" with respect of fire prevention, fire fighting and evacuation measures required at "Mechanical Post Graduate Block, M/s. RV College of Engineering, RV Educational Institutions, RV Vidyaniketana Post, Mysore Road, Bangaluru-560 059"- reg.

**Ref:** 1) Your request Letter dated: 03-11-2020.

2) Inspection Report No.85/DFO/NFS/Advice/20 dt:14/12/20.

\*\*\*\*\*\*

With reference to the subject cited above, the premises of "Mechanical Post Graduate Block, M/s RV College of Engineering, RV Educational Institutions, RV Vidyaniketana Post, Mysore Road, Bangaluru-560 059" was inspected by the District Fire Officer, North Fire Station, Bengaluru on 13-11-2020 with respect to Fire prevention, Fire fighting and Evacuation measures to be complied in the above premises and has submitted the details as under.

## A. Details of the building / premises :-

01	Name and Address of the		The PRINCIPAL,
	Applicant.		RV College of Engineering,
			R.V.Educational Institutions,
			R.V.Vidyaniketana Post, Mysore Road,
			Bangaluru-560059.
02	Name and Address of the premises.	:	Mechanical Post Graduate Block
			RV College of Engineering,
	E ILO OVE		R.V. Educational Institutions,
	Bengaluru &		R.V. Vidyaniketana Post, Mysore Road,
	S Bengaluru *	1	Bangaluru-560059.

	2				
03	Name and address of the	:	Rashtreeya Sikshana Samithi Trust		
	Building owner		R.V.College of Engineering		
	*		Bangalore59.		
04	Number of buildings	:	01 building i.e. Mechanical Post		
	-		Graduate Block.		
05	Number of floors	:	Basement +Ground+ 03 upper floors		
06	Floor-wise details of occupancy:-				
	Basement floor		Two Wheeler parking.		
	Ground floor	:	Class rooms-04, Wash rooms-02.		
	1 <sup>st</sup> floor	:	Class rooms-06, Wash rooms-02.		
	2 <sup>nd</sup> floor	:	Class rooms-04, Faculty-01, Wash rooms-		
			02, MEPG-01.		
	3 <sup>rd</sup> floor	:	Class rooms-02, wash rooms-02.		
07	Height of the building	:	14.10 mtrs.		
08	Site area	:	26 acres 19 kuntas.		
09.	Built-up area of each floor:-				
	Basement floor	:	276.456 Sq.mtrs		
	Ground floor	:	488.909 Sq.mtrs		
	1 <sup>st</sup> floor	:	438.770 Sq.mtrs		
	2 <sup>nd</sup> floor	:	430.637 Sq.mtrs		
	3 <sup>rd</sup> floor	:	447.052 Sq.mtrs		
10.	Total built-up area	:	2,081.824 Sq. Mtrs.		
11.	Surrounding properties:-				
	North (Front)	:	Bangalore Mysore High way road.		
	South (Rear)	:	Vrishabhavathi Naala		
	East(Side)	:	VRL BUS Garrage		
	West(Side)	:	Private Property		
12.	Set-back area available around the building :-				
	North (Front)	:	08 mtrs		
	South (Rear)	:	08 mtrs		
	East(Side)	:	08 mtrs		
	West(Side)	:	08 mtrs		

<u>Part-B</u>. On inspection of this Industrial premises, the following fire prevention, fire fighting and evacuation measures recommended are considered absolutely essential from fire safety point of view:-

SI. No. (1)	Details (02)	Existing (03)	Recommendations (04)
01.	Accessibility to the premises	The Premises is accessible from 24 mtrs wide Bangalore Mysore Highway road on Northern side and hard enough to carry the weight of 45.000.kgs.	Complied.

02.	No. of entrances	02 entrance & e. provided.	xit	has been	Complied.	
03.	Width of entry / exit	02 entrance & exit of 6.70 mtrs in Northern side has been provided from Bangalore mysore high way road.			Complied.	ā
04.	Diesel generators.	04 Diesel generators, one of 600 KVA capacity, 500 KVA capacity, 380 KVA capacity and 250 KVA capacity has been provided and connected to all staircase lighting, corridor lightings & other utilities.			Complied.	
05.	No. of staircases available	Nos. of staircases Width of staircases Width of treads Height of risers Nos. of riser per flight Height of handrails Head room clearance	: : : : : : : : : : : : : : : : : : : :	01 No.  1.50 mtrs each 30 cms 15 cms 15  1.10 mtrs	Complied.	
06.	No. lifts and capacity.	Nos. of lifts  Capacity of lifts	:	01 10 persons	Complied.	
07.	Fire extinguisher	04 Nos of ABC powder extinguishers, each of 6 kgs capacity, 05 Nos of water mist type of extinguishers, each of 4 kgs capacity, and 04 Nos of CO2 extinguishers each of 02 kgs has been provided in the each floor.			Complied.	
08.	Public address system	Public address system with two communication facility has been provided.			Complied.	
09.	First aid Hose reel hose.	Down comer system with 05 Nos. single headed hydrant outlet has been provided near the staircase at each floor. Hose reel hose of 40.00 mtrs length with a shut off branch has been provided near each hydrant outlet. The riser dia is 100 mm and GIC class pipe has been provided.			Complied.  Sengaluru Seast X Zone	
		has been provid hydrant outlet. The mm and GIC class	ed ri	near each ser dia is 100	Bengaluru Co East *	

10.	Manually operated electronic Fire alarm system.	Manually operated electrical fire alarm system with manual call points at each floor near the staircase landing have been installed and maintained with its fire alarm control at ground floor level.	Complied.
12.	Terrace tank over respective tower terrace.	The system has been connected to overhead tank of 25,000 liters capacity.	Complied.
13.	At the terrace tank level with minimum pressure of 3.5 kg/cm <sup>2</sup> .	The system has been connected to booster pump capable of delivering 900 LPM at minimum pressure of 3.5 kg/cm <sup>2</sup> installed near the overhead tank.	Complied.
14.	Automatic sprinkler system	Not provided.	Automatic sprinkler system with one sprinkler head for every 6.96 Sq.mtrs of built up area should be provided at basement.
15.	Fire control room at ground floor.	The fire control panel has been provided at ground floor.	Complied.
16.	Escape routes	Escape routes has been marked at each floor to guide the employees in case of any emergency.	Complied.
17.	Fire order	Notice board indicating with the details of action to be taken by the employees in case of any emergency/ fire has been displayed near the staircase landing at each floor with telephone number of North Fire Station i.e. 22971536 and 101 of nearby Services.	Complied.
18.	No smoking board.	Not displayed.	COTPA Sec-4, direction NO Smoking area smoking here is an offence board should be written in English & Kannada both language

	×		shall be prominently displayed at inside the entry / exit of the each floor.
19.	Fire fighting training	Not provided.	40% of the staff should be got trained in fire prevention and fire fighting evacuation measures at R.A Mundkur Fire & Emergency Services Academy, Bannerghatta road Bangalore.

# Fire precautionary measures :-

- A) Ex[plosive and flammable materials should not be stores in the store room, UPS room, Electrical panel area, class rooms, laboratory & electrical sum panel premises.
- B) Accumulation of combustible waste in and the premises should be avoided.
- C) The exit ways shall be always kept clear without any obstruction.
- D) Liquefied petroleum gas should not be stores in the building.
- E) The doors shall not be kept locked / latched during working hours and shall be free from obstruction.
- F) During the class hours the class room doors shall not be locked from inside to out side.
- G) As per Honorable Supreme Court order all teachers and staffs shall be trained to handle safety equipment, initiate emergency evacuation and protect their students in the event of fire and other emergency and the school shall observe the Fire Safety Day on April 14<sup>th</sup> of every year be conducting Fire Safety drills with co-ordinate Fire Service department.

Under the above circumstance, the Karnataka Fire & Emergency Services Department is issuing Fire Safety Recommendation to "Mechanical Post Graduate Block, M/s RV College of Engineering, RV Educational Institutions, RV Vidyaniketana Post, Mysore Road, Bangaluru-560 059" subject to condition stipulated above and compliance of the above recommendations as shown in Column-4 of serial-B within 3 months and compliance should be obtained from the undersigned.

"This Fire Safety Recommendation is valid for Only One Year from the date of issue and it is renewable.

All requirements recommended above are as per National Building Code-2016 Part-4 clause 3.1.6 of Fire and Life safety will have to be complied with mandatorily.

Copy to the District Fire Officer, North Fire Station, Bengaluru.



Yours faithfully,

Chief Fire Officer
Bengaluru East Zone
Bengaluru